


Phase Rotation Indicators

Product Images

Product Code: C72-4450



Short Description

The Martindale Phase Rotation Indicators quickly and simply proves the presence of all three live phases (or identifies which are faulty) and shows the sequence of phase rotation when all three phases are confirmed as present. Bright LED indication of live phases.

1

- Clear and simple display of the direction of phase rotation

- Easy identification of faulty lines
- No batteries required
- Retractable probe shrouds to GS38

Description

The Martindale Phase Rotation Indicators quickly and simply proves the presence of all three live phases (or identifies which are faulty) and shows the sequence of phase rotation when all three phases are confirmed as present. Bright LED indication of live phases.

It gives a fast, effective, battery-free method of identifying unmarked cables and ensures that 3-phase outlets and machines are wired correctly.

The retractable GS38 fused probe shrouds give a choice between long exposed tips, for reaching difficult to access contacts, and shorter tips for increased safety.

Supplied with L1 and L2 fused probes while L3 is a fused croc clip, the two-handed application is both safe and secure.

Optional colour coded and interchangeable croc clips for probes and probes for croc clips are available.

- Clear and simple display of the direction of phase rotation
- Easy identification of faulty lines
- No batteries required
- Retractable probe shrouds to GS38