



A RIPLEY® BRAND

MB03-7010 ROC DROP SLITTING TOOL Instruction Sheet

Part # MB03-7010


Page 1 of 1

WARNING: THIS TOOL SHOULD NOT BE USED ON LIVE ELECTRICAL CIRCUITS. IT IS NOT PROTECTED AGAINST ELECTRICAL SHOCK!
ALWAYS USE OSHA/ANSI/CE OR OTHER INDUSTRY APPROVED EYE PROTECTION WHEN USING TOOLS. THIS TOOL IS NOT TO BE USED FOR PURPOSES OTHER THAN INTENDED. READ CAREFULLY AND UNDERSTAND INSTRUCTIONS BEFORE USING THIS TOOL.

The ROC DROP Slitting Tool will make an error-free, precise separation of the toner wire from Corning ROC DROP fiber cable. The tool can be used on a mid section of the cable or the cable end.

Seat the cable flat into the tool body with the toner wire toward the blade. Close the handle fully. Slide the tool in either direction to separate the toner wire.

Replacement Slitting Blade: CB 209



WARRANTY: RIPLEY warrants its products against defective materials and workmanship for a period of one year from date of shipment from the RIPLEY factory provided the product is utilized in accordance with instructions and specified ratings.



RIPLEY®

Ripley Tools LLC
46 Nooks Hill Road, Cromwell, CT 06416

P: +1 (800) 528-8665
F: +1 (860) 635-3631

csr@ripley-tools.com
www.ripley-tools.com

Doc. No.	MB03-6001
Approval:	03-22-18